Arborist Report 600 Haight Avenue

| Date: | February 14, 2024 |
|-----------------|------------------------------------------------------------------------------------------|
| То: | Erin Smith, Public Works Director 950 West Mall Square, Room 110 Alameda, CA 94501 |
| Subject: | 600 Haight Avenue |
| Species: | Fraxinus spp Ash Tree |
| Recommendation: | Removal – Hazard |

Summary:

The tree root has loss 60% of holding roots this creates a total tree failure with the risk of damage to public and private property. There is an urgent safety threat. The tree was inspected on February 14, 2024.

Photo:



Prepared by: Jesse Barajas, EMPA

WCISA Certified Arborist # 4394A Qualified Applicator/ DPR # 91794

950 West Mall Square Alameda, CA 94501 Phone (510) 747-7966, Fax (510) 521-8762 E-mail: jbarajas@alamedaca.gov