

Arborist Report
2719 Calhoun Street

Date: April 18, 2024

To: Erin Smith, Public Works Director
950 West Mall Square, Room 110
Alameda, CA 94501

Subject: 2719 Calhoun Street



Species: Syagrus romanzoffiana- Palm Tree

Recommendation: Removal – GO95 Hazard Tree (Three Week Notice)

Summary:

The tree is the cause of electrical hazard per **GO 95, Rule 56.7-B, Location of Sectionalizing Insulators**, this creates a hazardous condition and requires its removal for the safety of the general public or to prevent significant damage to property. The tree was inspected on April 18, 2024.

Photo:



Prepared by:

Jesse Barajas, EMPA
WCISA Certified Arborist # 4394A
Qualified Applicator/ DPR # 91794

950 West Mall Square
Alameda, CA 94501
Phone (510) 747-7966, Fax (510) 521-8762
E-mail: jbarajas@alamedaca.gov